

GOVERNMENT OF PUERTO RICO/OFFICE OF THE GOVERNOR ENVIRONMENTAL QUALITY BOARD EMERGENCY RESPONSE AND SUPERFUND AREA

5 ite Inspection Report

May 20, 1998

Mr. Juan E. Dávila
Project Manager
Emergencies Remedial Response Division
Program Support Branch
Technical Pre-Remedial Support Section
US ENVIRONMENTAL PROTECTION AGENCY
290 Broadway 18 th Floor
New York NY 10007-186

Dear Mr. Dávila

Re: B & B Woodtreating Saint Just Industrial Park Trujillo Alto, Puerto Rico

987379344

The B & B Woodtreating and Processing was located in the Saint Just Industrial Park in Trujillo Alto, Puerto Rico. The geographic coordinates are 18°22'42" N latitude and 66°00'09" W longitude. The site is surrounded by other industries, consists of approximately 2.5 acres and is located on relatively flat terrain that drain toward the Blasina creek. The company was established in 1976 for the treatment and preservation of wood. On 1989, as consequence of Hurricane Hugo that destoyed the old site structures, they moved to the Amelia Industrial Park in Guaynabo.

On June 3, 1992 under the authority of the Comprehensive Environmental Response, Compensation and Liability Act of 1980 (CERCLA) and the Superfund Amendment and Reauthorization Act of 1986 (SARA), the Puerto Rico Environmental Quality Board conducted a Preliminary Assessment (PA). The inspection revealed that the B & B Woodtreating facility operated from 1976-1989. The site consisted of four (4) structures: one for wooden doors manufacturing and raw material storage area; second one for maintenance area and a treated wood dehumidifier; third were the offices, machinery, treating cylinders and tanks; fourth was a wood

Juan E. Dávila

B & B Woodtreating

Page 2 May 20, 1998

storage area. During the years of operation they used a mixture of chromium cooper arsenate (CCA),

and water as preservative, reason why samples were taken from the site. The results of the samples

collected, states high levels of chromium, cooper and arsenate. Due to the irregularities found during

the preliminary assessment, a Site Inspection (SI) was recommended.

Then, on May 8, 1998 the PREQB Superfund technicians conducted an onsite

reconnaissance which revealed that the site was bought by Mr. Otero, five months ago, who is using

it to store alumina. This substance is sold to the PR Aqueduct Sewer Authorithy to treat the water

from their filter plants. Mr. Otero also informed, that he removed the soil and the water from the

pit; then, covered the area with more than four feet of earthen material and gravel. While, the others

areas in the facility are covered with cement and asphalt. Due to the fact that the source area was

covered with a new layer of soil, and there are not drinking water wells within a 4-miles

downgradient to the site, or surface water intakes 15 downstream miles from the site, a No Further

Remedial Action Plan (NFRAP) is recommended under the Superfund program.

Sincerely,

Jorge L. Quiñones

Superfund Program

PA/SI Acting Chief

NHM/dcb

ON SITE RECONNAISSANCE INFORMATION REPORTING FORM

Date:

May 8, 1998

Site Name:

B & B Woodtreating

Saint Just Industrial Park Trujillo Alto, Puerto Rico

PREQB Superfund PA/SI technicians, Nereida Hernández, Mercedes Padilla and Jorge L. Quiñones, arrived to the site, in order to perform a reconnaissance. To reach the site, travel south from San Juan on Muñoz Rivera Ave. until reach State Road #3 (Regimiento 65 de Infantería), then travel east until the intersection with State Road #181 and turn to the right. Travel southward until the intersection with State Road #848. In the next turning make a left and travel up to Km. 1.8 where the entrance to the Saint Just Industrial Park is located. Turn to the right and then to the left. The site is located to the right.

- 1237 Interview with Mr. Alberto Otero, son of the owner. He informed that they bought the property five months ago. There are six workers onsite. The facility has been used to store alumina which is sold to PR Aqueduct and Sewer Authorithy to treat the water from their filter plants. The new name of the facility is SYS, Inc.
- 1247 Were taken the photos of the site.
- Mr. Grego A. Otero, the new owner of the facility arrived to the site. He informed that, after he bougth the property, the water of the pit and the soil from the surrounding areas were removed, and then covered with a new layer of soil (more than four feet) and gravel.
- 1322 Finished the Onsite Reconnaissance.

ON SITE RECONNAISSANCE INFORMATION REPORTING FORM

Date:

May 8, 1998

Site Name:

B & B Woodtreating

Saint Just Industrial Park

Trujillo Alto, Puerto Rico

Camera:

Canon T-5

Film:

Kodak Gold 100 / 36 films

Photographer:

Nereida Hernández

PHOTOLOG

PHOTO/NUMBER	TIME	DESCRIPTION
1 - 3	1247	Storage area of alumina (drums - 55 gals.).
4 - 5	1256	Front part of the facility covered with asphalt and cement.
6 - 7	1259	Back part of the facility covered with a new layer of soil and gravel.
8	1305	Area where the pit with water was located.



PHOTO 1




PHOTO 2



РНОТО 3



PHOTO 4



РНОТО 5



PHOTO 6



PHOTO 7



PHOTO 8